

Oil Field Environmental Incident Summary

Incident: 20140807094140

Date/Time of Notice: 08/07/2014 09:41

Responsible Party: T & R Trucking

Well Operator: HRC OPERATING, LLC

Well Name: SIIRTOLA 1 SWD

Field Name: STRANDAH

Well File #: 90227

Date Incident: 8/6/2014

Time Incident: 17:45

Facility ID Number:

County: WILLIAMS

Twp: 157

Rng: 102

Sec: 28

Qtr: NW NW

Location Description: Constructed Well Pad - Within Secondary Tank Battery Containment

Submitted By: Kelly Grimm

Received By:

Contact Person: Soren Bostad
12125 ND Hwy 5
Crosby, ND 58730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|-------|---------|---------|-----------|---------|----------|---------|
| Oil | | | | | | |
| Brine | 15 | Barrels | 15 | Barrels | 15 | barrels |
| Other | | | | | | |

Description of Other Released Contaminant:

NA

Inspected:

Written Report Received: 11/27/2015

Clean Up Concluded: 8/10/2014

Risk Evaluation:

No impacts beyond secondary containment

Areal Extent:

Within Secondary Containment

Potential Environmental Impacts:

Impacts limited to secondary containment soils

Action Taken or Planned:

A super suction on location for cleaning operation immediately sucked up fluid.

Wastes Disposal Location: Fluids back into same SWD. Soils will go to approved E&P disposal.

Agencies Involved:**Updates**

Date: 9/26/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.